

OIL FILTERS



ACCESSORIES

OIL DRAIN KITS

For easy installation this kit includes:

- 42" hose with hose hanger
 - Universal oil pan replacement plug
 - End cap
- ✓ Makes changing your oil a snap and without the mess!
 - ✓ Permanently mounts to bottom of oil pan to make changing oil more convenient.
 - ✓ Drains 4 quarts of oil in less than 15 minutes without a pump.
 - ✓ Fittings on hose machined from corrosion resistant brass.
 - ✓ Assembly sized to pass through most common hull drains.



OIL DRAIN KITS

Total Length 42 Inches

Sierra#	AP #	Description
18-7891	1801	For: GM, Chrysler & Most Ford Oil Pans 1/2" — 20 Threads
18-7892	1896	For: European Made Volvo Engines 3/4" — 16 Threads

OIL DRAIN ADAPTERS



18-7893 OIL DRAIN ADAPTER

Machined from Corrosion Resistant Brass

18-7893[Ⓛ] For: Some Ford Block Marine Engines
14 mm x 1.50 Threads

[Ⓛ] Remove adapter from 18-7891/AP# 1801 or
18-7892/AP# 1896 & replace



18-9789
OIL FILTER WRENCH
2-9/16 3-1/4



18-9790
OIL FILTER WRENCH

Oil Filters

Features...

- ★ Manufactured to meet or exceed OEM specifications.
- ★ High Efficiency Filters.
- ★ Field-tested and approved.
- ★ Anti-Drainback valves where required.



OIL FILTERS

ACCESSORIES

Diesel Oil Filters									
Sierra#	AP #	Specifications	Replaces:	O. E #	Sierra#	AP #	Specifications	Replaces:	O. E #
18-7871	—	—	Mer cruiser	35-805809	18-7910	6033	Thread Spec.		
18-7874	—	—	Cummins	299670			20 mm. x 1.5	Westerbeke	30220
18-7880	—	—	Caterpillar	1R-0658			Anti-Drainback Valve	Yanmar	124450-35100
			Volvo-Penta	466634-3	18-7886	—	(Short Filter)	Perkins	2654403
18-7883	—	(Large Diameter) Universal 1 cyl.,2 cyl., 3 cyl. Thread Spec. 20 mm. x 1.5					Thread Spec. 3/4" x 16 NPT		
					18-7887	6032	(Tall Filter)	Perkins	2654347, 2654407
18-7884	—	Thread Spec. 3/4" x 16 NPT	Universal	299381			Thread Spec. 3/4" x 16 NPT		
		Anti-Drainback Valve	Volvo-Penta	834337	18-7899	—	Anti-Drainback Valve		
			Suzuki	16510-87J00				Detroit Diesel	25010495

Sterndrive & Inboard Oil Filters		
Sierra #	AP #	Specifications
★ 18-7824	6003	Thread Spec 13/16" x 16 NPT No Anti-Drainback Valve—(Short GM) GM 4-cyl. 6 cyl. Inline V-8 (The 18-7824 is a short canister filter that can be used in all previous 18-7877 applications) Replaces: Chris-Craft 16.81-08746 / Crusader 201104 / Indmar 50-1001 / Mercruiser 14957*, 54111*, 35-802885Q*, 32716* / OMC 1732332 / Pleasurecraft R077002 / Volvo-Penta 835440-9
★ 18-7875	6007	Thread Spec. 3/4" x 16 NPT Anti-Drainback Valve—(Long Ford) Ford 4 cyl. 2.3L V-8 302,351 Replaces: Chris-Craft 16.81-06536 / Chrysler 1851658 / Crusader 9002514 / Mercruiser 60565 / OMC 173231 / Pleasurecraft R077001
★ 18-7876	6005	Thread Spec 13/16" x 16 NPT No Anti-Drainback Valve—(Long GM) GM V-8 Replaces: Mercruiser 35-16595T1, 52731 / OMC 173233
★ 18-7878	6008	Thread Spec. 3/4" x 16 NPT Anti-Drainback Valve—(Short Ford) Replaces: Volvo-Penta 1266286-2, 430143-8, Chrysler 3549957, L 19, L-1008
★ 18-7879	6004	Thread Spec. 18mm x 1.5 Anti-Drainback Valve (V-6 GM) Replaces: Chrysler L-319 / Mercruiser 35-802884Q, 41815 / OMC 173834

4 Cycle Outboard Oil Filters		
Sierra #	AP #	Specifications
18-7901	—	9.9 4 stroke S/N H000058-H017099 (1995-98) F & T 9.9 (1990-02) Replaces: Mercury 825467A1, 825467T1 Replaces: Yamaha 6G8-13440-00-00
18-7916	—	Replaces Johnson/Evinrude 434839
18-7911	—	BF25, BF30,A,AW,AX,AY, Series #14ZV90E1M BF35/45AM, BF40/50A,AW,AX Series # 14ZV50M Replaces: Honda 15400-PFB-004, Nissan 3RO-07615-0, Tohatsu 3RO-07615-0, Yamaha 5GH-13440-00-00
18-7910	—	BF75, BF90,AT,AW,AX,AY, Series #14ZV00E1M BF115, BF130, AX,AY,A1 Series # 14ZW5E1M 75 HP & up Replaces: Honda 15400-POH-305PE, 15400-POH-30
18-7913	—	Mercury 4-Stroke O/B's, 9.9/15 and 8/15 Bodensee OG760300 & UP Replaces: Mercury Outboard 35-822626Q 1
18-7914	—	Mercury 4-Stroke O/B's, 25/30/40/45/50HP S/N OG760300 & UP, 75/90HP - S/N OG960500 and UP Replaces: Mercury Outboard 35-822626Q 2
18-7915	—	DF25, DF30, DF40, DF50, DF60, DF70, 4-stroke (99-02) 40/50, (00,01) 25/30, (01-03) 70, (02,03) 60 4-stroke Replaces: Suzuki 16510-82703 Replaces: J/E/Bombardier 5031411
18-7902	13528	F15 (1998-2001) F40 (1999-2001) F25 (1998-1999) F & T50 (1995-1998) F80 (1999-2001) F100 (1999-2001) Replaces: Yamaha 3FV-13440-00-00
18-7906	—	Yamaha 69J-13440-00-00 For: F200/F225
18-7903	—	Suzuki 16510-05240 For: DF9.9, DF15

★ Display Packaged * Except V-6 with remote oil filter

OIL FILTERS



ACCESSORIES

Oil Filter Application			
Make—Model—Year	Sierra Oil Filter	Make—Model—Year	Sierra Oil Filter
Albin AD-21 SPIN ON LUBE Replaces: ALBIN 3875827	18-7878	Detroit Diesel (cont.) 12V-149 (1788), 16V-71 (1136), 16V-71T (1136), 16V-92 (1472), 16V-92T (1472), 16V-149 (2384) Series Replaces: Detroit Diesel 25010495	18-7899
B & W Lathrop 130155 SPIN ON LUBE	18-7875	Evinrude Explorer (w/V8-350), Rogue (w/V8-307), w/V8-327) SPIN ON LUBE Replaces: OMC 173233 Replaces: OMC 173233 Replaces: OMC 173232	18-7824 18-7824 18-7824
Caterpillar 3304, 3306, D330 Replaces: Caterpillar 1R-0658	18-7880	Flagship 150FA, 220FF, 250FA, 400FA, 425FAJ, 650FAJ, 950FAJ SPIN ON LUBE	18-7824 18-7824 18-7824
Chris-Craft 307G, 305K,307K SPIN ON LUBE Replaces: Chris Craft 16.81-08746	18-7824	292, 300, 307, 327, 350, 482 SPIN ON LUBE	18-7876 18-7824
Chrysler (Chrysler-Volvo) 100, 110, 120, 130, 165, 170 SPIN ON LUBE	18-7878	Ford CSG850M WSG858M,LSG875M,SSD-655, -655M, -655MT, (5.5 Liter), 140(2.3L) FOUR, 170, 200 Six, 240 Six, 300 Six, 302 (5.0L),351 (5.8L), 460 (7.5L),2711E, 2712E, 2713E, 2714E, 2715E (diesel) SPIN ON LUBE	18-7875
125, 150, 155, 175, Fury 190, 195, 200, 210,225, 235, 250, 260, 280, 300, 330, 335, 375, 525, CM6-55, CMC-55NA, M-170A, M-225A, M-225D, M-273A, M-273B, M-273BO/D, LM-318, LM-318A, LM-318B, M-318B, M-318C, M-383B, M-413B, M-413D, M-413E, M-440B, M-440D, Model 340,M-80, M-81, Super Crown 145, 150, Imperial 290, 325, Jet II, Jet III, Jet IV, Super Bee, Super Bee II,Super Bee III, V-8 Engines 1962-on SPIN ON LUBE Replaces: Chrysler 1851658	18-7875	254 (DSD-442 4.2 Liter), 362 (DSD-659 5.9 Liter) REMOTE SPIN ON LUBE	18-7875
3.7L, 5.2L Replaces: Chrysler 3549957 L-19, L-1008	18-7819	91—V4, 104 V4, 380 (DSD-662 6.2 Liter) SPIN ON LUBE	18-7878
Commander 225, 340 Clever SPIN ON LUBE	18-7875	GM 6-194 (1962-67), 6-230 (1963-68), V8-305 (1976-78), V8-307 (1970-73), V8-350 (1970-87), V8-366 (1970-87), V8-400 (1971-72, 1975-83), V8-454 (1973-87) SPIN ON LUBE	18-7824 18-7876
Crusader 150, 160,165, CH185, 210, CH220, CH270, 350, CH350 SPIN ON LUBE Replaces: Crusader 201104	18-7824	V8-267 (1979-81), V8-305 (1979-87), V8-350(1978-81), V8-400 (1974-77) SPIN ON LUBE	18-7824
SS330 REMOTE MOUNT SPIN ON LUBE Replaces: Crusader 201104 Replaces: Crusader 201104	18-7876 18-7824 18-7824	Greenwich Porpoise (w/IH V8-275B) SPIN ON LUBE	18-7875
220 Conquerer,255 Conquerer, 255 Conquerer Jet, 250 (71), 300 Scorpion, 460 SPIN ON LUBE	18-7875	Honda BF25, BF30, A,AW,AX,AY Series# 14ZV90E1M, BF35/45M, BF40/50A,AW,AX, Series #14ZV50M Replaces: Honda 1500-PFB-004 BF75, BF90, AT,AW,AX,AY, Series # 14ZW00E1M, BF115, BF130, AX,AY,A1, Series # 14ZW50E1M 75 HP & up Replaces: Honda 15400-POH-305PE, 15400-POH-305 SPIN ON LUBE	18-7911 18-7910
220, 300, 320,325 REMOTE MOUNT SPIN ON LUBE	18-7878	Hydro-Marine All Models (Knecht FO335/1) SPIN ON LUBE	18-7875
Cummins V-555, VT-555, N-855, NT-855, NTA-855, V-903, VT-903, VTA-903, KT-1150, KTA-1150, VT-1710, VTA-1710, KT-2300, KTA-2300, KTA-3067 Replaces: Cummings 299670	18-7874	Indmar 250 SPIN ON LUBE	18-7875
Daytona 200, 292, 300, 350,400, 427,427A,427B SPIN ON LUBE	18-7824 18-7876 18-7824	275 (SP), 300 (SP) , 350-2, 350-4, 350(SP), 454-2, 454-4, 400 (SP) SPIN ON LUBE	18-7876 18-7824
Detroit Diesel 2-71 (142), 3-71 (213), 4-53 (212), 4-71 (284), 6V-53 (318), 6-71 (426), 6-71E (426), 671N (426), 6-71T (426), 6V-71 (426), 6V-71T (426), 6V-92 (552), 6V-92T (522), 8V-71 (568), 8V-71T (568), 8V-92 (736), 8V-92T (736), 12V-71 (1788), 12V-71T (1788),			



OIL FILTERS

ACCESSORIES

Make—Model—Year	Sierra Oil Filter	Make—Model—Year	Sierra Oil Filter
Interceptor IV4-80, OV4-80, OV6-100 (Taunus), 80, 85, 100, 110, 120, (1960-on), 140, 190, 200, 210, Interceptor 160, Interceptor 165 SPIN ON LUBE	18-7878	Mercury/Mariner (Cont.) OG760300 & Up, 75/90HP s/n OG960500 & Up Replaces: Mercury 35-822626Q 2	18-7914
Johnson Surfer (w/V8-327) SPIN ON LUBE Replaces: OMC 173233 Replaces: OMC 173232 Replaces: 434839	18-7824 18-7876 18-7824 18-7916	Mohawk V8-302, V8-351 SPIN ON LUBE	18-7875
Lehman Models (w/Ford 242), (w/Ford 254), (w/Ford 363), (w/Ford 380), (Lehman 2N50) SPIN ON LUBE	18-7875	Nissan All 4 stroke engines Replaces: 3RO-07615-0	18-7911
Marine Power, Inc. 3.0L, 350 (5.7L) 454 (7.4L) ENPACK Replaces: Marine Power 0905-000-0	18-7824 18-7876 18-7824	OMC 170 (1974), 175 (1975-77) 190 (1974-77), 235 (1975-77) 240 (1978), 2.3L (1987), 7.5L (1987) SPIN ON LUBE Replaces: OMC 173231	18-7875
Mercuriser 60, 80 SPIN ON LUBE	18-7878	205, 229 (Chevrolet V6), 175 3.8L (1981), 4.3L (1986) SPIN ON LUBE Replaces: OMC 173834	18-7879
175, 185, 205 Replaces: Mercuriser 41815, 35-802884Q	18-7879	M-100, M-200 (1961-on) SPIN ON LUBE	18-7878
88 (188), 215, 233, 235, 250, 255 225, 225-S Replaces: Mercuriser 60565, 35-802886Q	18-7875	210 (1970), 100 (1973), 165 (1973-76), 2.5L (1982-86), 3.0L (1982-87), 120, 140 (1973-81) SPIN ON LUBE Replaces: OMC 173232	18-7824
160, 470 (170), 485 (185), 488 (188) 190 SPIN ON LUBE Replaces: Mercuriser 54111 Replaces: Mercuriser 14957 190, 898 (198), 225, 270, 390 REMOTE MOUNT SPIN ON LUBE Replaces: Mercuriser 14957 Replaces: Mercuriser 52731, 35-16595T1 Replaces: Mercuriser 54111, 35-802885Q	18-7824 18-7824 18-7876 18-7824	165 (1972), 185 (1978-80), 200 (1979-81,) 210 (1971-72) 225 (1973-76, 78), 230 (1975-76, 1978-81), 245 (1973-75), 250 (1970-72), 260 (1975-76, 1979-81), 290 (1974-75), 305 (1977-80, 82), 350 (1977-80, 82) 454 (1977-82) 5.0L (1982-present) 5.7L (1982-present) SPIN ON LUBE Replaces: OMC 173233 Replaces: OMC 173232	18-7824 18-7876 18-7824
120, 140, 150, 160, 165, 170, 180, 200, 230, 250, 300, 320 EFI, 325, 340, 350, 370, 350 MAG, 454 MAG, 400, 525, 2.5L, 3.0L, 5.0L, 5.7L, 7.4L, 228, 260, 280, 255, 330 SPIN ON LUBE Replaces: Mercuriser 14957 Replaces: Mercuriser 52731 Replaces: Mercuriser 54111	18-7824 18-7876 18-7824	OMC / Bombardier (99-02) 40/50 4 stroke (00,01) 25/30 4 stroke (01-03) 70 4 stroke (02,03) 60 4 stroke Replaces: OMC/Bombardier	18-7915
7.3L/270 Diesel 7.3L Bravo Diesel Replaces: Mercuriser 35-805809, 35-805809T	18-7871	Onan JA, JB, JB (Ind. eng.), JC gen., JC (Ind. eng.), MJA, MJB, MJC, J-30, J-60, J-120, RDJF, RJC, DJA, DJB, DJC, MDJA, MDJB, MDJC, RDJC, DJ-30, DJ-60, DJ-120, JD-130 MDJ-30, MDJ-130, 6MDJB-37, 15MDJC-3R, 3.0 DJA, DJE, 6.0 DJB, MDJE, MDJF, NH, 7.5 MDJE, 15MDJF, 15 MDJ-3R, 705 MDJE-3R, 150 MDJF, DJB Gen. (Standard) SPIN ON LUBE Replaces: Onan 122-0185	18-7878
Mercuriser Diesel 0219 Turbo Diesel Blue Water (Bravo Series) D254 Turbo Diesel Blue Water (Bravo Series) SPIN ON LUBE Replaces: Mercuriser FIAAMFT4805	—	EF SPIN ON LUBE	18-7875
Mercury/Mariner 9.9 4 Stroke S/N H000058-H017099 Replaces: Mercury 825467A1, 825467T1 4 Stroke O/B's, 9.9/15 & 8/15 Bodensee OG760300 & Up Replaces: Mercury 35-822626Q 1 4 Stroke O/B's, 25/30/40/45/50HP s/n	18-7901 18-7913	Onan (Generator Sets) 3.0 Aux. (w/MDJA diesel eng.) SPIN ON LUBE Replaces: Onan 122-0185	18-7878
		Palmer AD-21 SPIN ON LUBE	18-7878
		P302, P351, P460, PA190, PA220, PA255 SPIN ON LUBE	18-7875

OIL FILTERS



ACCESSORIES

Make—Model—Year	Sierra Oil Filter	Make—Model—Year	Sierra Oil Filter
Perkins 4.154M, 4.154/165, 4.203, 4.236, 4.236, 4A236, 4.248, 4.300, A4300, A4.318 (Except A4-318), 6.247, 6.354, 6.354M, T6.354, T6.354M, HT6.354, HT6.354M, 6.3544, T6(.354, ST6.3544 Ranger 4 Series: 6.372, 6/152, 3/152Y, 3AB152, 4.107, 4.107M, 4.108, A4-212, AG4-212, 6.354.2 Replaces: Perkins 2654347, 2654347 Replaces: Perkins 2654403	18-7887 ② 18-7886 ③	Volvo-Penta (Cont.) TAMD31A, MB20A, MB20B, MB20C, MD21A, AQAD30A, AQAD31A, AQAD21A SPIN ON LUBE Replaces: Volvo 1266286-2	18-7878
Pleasurecraft PCM Model 200, 220, 250, 8200, 8240 SPIN ON LUBE Replaces: Pleasurecraft R-077001	18-7875	TAMD100, TAMD122, TAMD162, TMD102,TMD121, TMD122 Replaces: Volvo 466634-3	18-7880
PCM Model 230, 280, 300, 350 SPIN ON LUBE Replaces: Pleasurecraft R-077002	18-7824 18-7876 18-7824	AQ175A, AQ200B, AQ200C, AQ200D, AQ200F, AQ225B, AQ225C, AQ225D, AQ225E, AQ225F, AQ255A, AQ255B, AQ260B, AQ271A, AQ290A, AQ260A, AQ311A SPIN ON LUBE Replaces: Volvo 835440-9	18-7824 18-7876 18-7824
Ranger 85, 110 SPIN ON LUBE	18-7878 18-7904	20001, 2002, 2003, 2003T, MD6, A, B, MD7, A, B, MD11C, D, MD17C,D Replaces: Volvo 834337	18-7884
Suzuki DF9.9, DF15 Replaces: Suzuki 16510-05240	18-7903	Waukesha 155, 165, 185, 215, 255, 302, 351 SPIN ON LUBE	18-7875
DF25, DF30, DF40, DF50, DF60, DF70 Replaces: Suzuki 16510-87J00	18-7915	Westerbeke Four-60, Four-91, Four-154, BR-30, BR-45, Performer-6, WPDS-10, WPDS-20 SPIN ON LUBE	18-7875
Tohatsu All 4 stroke engines Replaces: 3RO-07615-0	18-7911	D60, D80, 10 TWO, 13A, 18, 21 (A), 27 (A), 33, 41G, W70G Replaces: Westerbeke 30220	18-7885
Universal 16510-82703 Strato King V8-350 SPIN ON LUBE	18-7878	Yamaha All V8's, 5.0L, 5.7L SPIN ON LUBE	18-7824 18-7876 18-7824
M-15 1Cyl., 2 Cyl., 3 Cyl,	18-7884 18-7882 ④ 18-7883 ⑤	All V6's, 4.3L SPIN ON LUBE	18-7879
Volvo-Penta BB30, BB100, BB115A, BB115B, BB115C, BB140A, BB145A, BB165A, BB170A, BB170C, AQ60F, AQ90, AQ95, AQ95A, AQ100, AQ110, AQ115A, AQ115B, AQ120, AQ120B, AQ125A, AQ125B, AQ130A, AQ130C, AQ130D, AQ130E, AQ131A, AQ140A, AQ145A, AQ145B, AQ151A, AQ151B, AQ165A, AQ170A, AQ170B, AQ170C, AQ171A, MB18, MB18F, MD30A, MD31A, TMD30A, TAMD30A, TMD31A,		F15 (1998-1999), F40 (1999), F25 (1998-1999), F & T 50 (1995-1998), F80 (1999), F100 (1999) F & T 9.9 (1990-99) Replaces: Yamaha 6G8-13440-00-00	18-7902
		F200/F225 Replaces: 69J 133440-00-00	18-7906
		F15 (2000-03), FT25 (2000-03) F40 (2001-03), F/T50 (200-03) F60/F80/F100 (2000-03) F115 Replaces: 5GH-13440-00-00	18-7911
		Yanmar 1GM, 1GM10, 2GM, 2GMF, 2GM20, 2GM20F, 3GM, 3GMF, 3GM30, 3GM30F Replaces: Yanmar 124450-35100	18-7885

② Tall Filter

③ Short Filter

④ Small Diameter

⑤ Large Diameter

